

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

REVIEW SHEET

B-4218

Historic Preservation Certification Application—Significance

Address: 828 PARK AVENUE, BALTIMORE, MARYLAND Project No.: _____

Historic District: MOUNT VERNON

7-20-88 date initial application received by State _____ date(s) additional information requested by State

7-20-88 date complete information received by State _____

_____ date of this transmittal to NPS _____

Inspection of property by State staff? ☐ no ☒ yes date(s): 6-6-88

☒ There is adequate documentation enclosed to evaluate the historic character and integrity of this property.

_____ There is insufficient documentation to evaluate the property adequately. The application is missing the following items:

Reasonable efforts have been made to obtain this information. Copies of the information requests are enclosed.

NUMBER	This property involves:												
1	<table><tr><td>_____ Extensive loss of historic fabric</td><td>_____ Obscured or covered elevation(s)</td></tr><tr><td>_____ Substantial alterations over time</td><td>_____ Moved property</td></tr><tr><td>_____ Preliminary determination of listing</td><td>_____ State recommendation inconsistent with NR documentation</td></tr><tr><td>_____ for district</td><td>_____ Recommendation different from the applicant's request</td></tr><tr><td>_____ for individual property</td><td></td></tr><tr><td>_____ Significance less than 50 years old</td><td></td></tr></table>	_____ Extensive loss of historic fabric	_____ Obscured or covered elevation(s)	_____ Substantial alterations over time	_____ Moved property	_____ Preliminary determination of listing	_____ State recommendation inconsistent with NR documentation	_____ for district	_____ Recommendation different from the applicant's request	_____ for individual property		_____ Significance less than 50 years old	
_____ Extensive loss of historic fabric	_____ Obscured or covered elevation(s)												
_____ Substantial alterations over time	_____ Moved property												
_____ Preliminary determination of listing	_____ State recommendation inconsistent with NR documentation												
_____ for district	_____ Recommendation different from the applicant's request												
_____ for individual property													
_____ Significance less than 50 years old													

NUMBER	Complete item(s) below as appropriate.
2	<p>(1) The documentation on file with the National Register cites the period(s) of significance of this historic district as <u>19TH & 20TH</u></p> <p>(2) The property <input checked="" type="checkbox"/> contributes _____ does not contribute to the historic significance of this registered historic district in: <input checked="" type="checkbox"/> location <input checked="" type="checkbox"/> design <input checked="" type="checkbox"/> setting <input type="checkbox"/> materials <input checked="" type="checkbox"/> workmanship <input type="checkbox"/> feeling <input type="checkbox"/> association _____ Property is mentioned in the NR or State or local district documentation in Section _____, page _____.</p> <p>(3) For properties less than 50 years old: _____ the historical merits of the district (the periods and areas of significance) are documented in the National Register form or district documentation on file as less than 50 years old, justifying the certification of this property's contribution. _____ the exceptional historical or architectural significance of this property as described in the National Register form or district documentation on file justifies its certification as contributing. _____ there is insufficient justification to consider this property as contributing to the district for its individual exceptional architectural or historical significance or the significance of the district does not extend to the last 50 years.</p> <p>(4) For preliminary determinations: A. The status of the nomination for the property/historic district: _____ Nomination has already been submitted to State review board, and nomination will be forwarded to the NPS within _____ months. (Draft nomination is enclosed.) _____ Nomination was submitted to the NPS on _____. _____ Nomination will be submitted to the State review board within twelve months. _____ Nomination process likely will be completed within thirty months. _____ Other, explain: _____</p> <p>B. Evaluation of the property: _____ Property is individually eligible and meets National Register Criteria for Evaluation _____ Property is located within a potential registered district that meets National Register Criteria for Evaluation: <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D Criteria Considerations: <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G</p> <p>(5) The property is located in a registered district, is outside the period(s) or area(s) of significance as documented in the NR form and: _____ appears to contribute to the expanded significance of the district. Enclosed is the revised nomination documentation. _____ does not appear to contribute to the period(s) or area(s) of significance of the district.</p>

NUMBER

3

Describe and evaluate the physical characteristics of the property, its integrity, and its significance within the context of the historic district, (or individually for preliminary determinations of individual listings).

BUILT CIRCA 1840, THIS FREESTANDING BRICK TOWNHOUSE ORIGINALLY CONSISTED OF TWO STORIES OVER A RAISED BASEMENT WITH A TWO STORY ELL SECTION. THE ROOF WAS RAISED TO A FULL THIRD STORY APPROXIMATELY 1855. AT THAT TIME, AN ITALIANATE CORNICE WAS ADDED. NO OTHER CHANGES ARE EVIDENT ON THE EXTERIOR.

THE ONLY MODIFICATION MADE TO THE INTERIOR OCCURRED WHEN THE BUILDING WAS CONVERTED FOR USE AS A DOCTOR'S OFFICE AND APARTMENTS IN 1946. VIRTUALLY ALL OF THE WOOD TRIM, MANTELS, DECORATIVE PLASTER AND PANELING REMAIN INTACT AND IN GOOD CONDITION.

ALSO INCLUDED WITH THIS PROPERTY IS A BRICK, TWO STORY CARRIAGE HOUSE AT THE REAR. IT IS FAIRLY NON-SCRIPT AND TOTALLY UTILITARIAN ON THE INTERIOR. THE CARRIAGE HOUSE NEXT DOOR TO THIS PROPERTY AND SITUATED TO THE REAR OF A VACANT LOT, HAS HAD MANY ALTERATIONS INCLUDING MASSIVE

NUMBER

4

State Official Recommendation:

STRUCTURAL CHANGES (STEEL BEAM, ETC). IT IS ALSO FAIRLY NON-SCRIPT.

This application for the above-named property has been reviewed by MICHAEL DAY

a professionally qualified architect, architectural historian, or historian on my staff.

- ☒ The property is included within the boundaries of a registered historic district, contributes to the significance of the district, and is a "certified historic structure" for the purpose of rehabilitation.
- ☐ The property is included within the boundaries of a registered historic district, contributes to the significance of the district, and is a "certified historic structure" for a charitable contribution for conservation purposes in accordance with the Tax Treatment Extension Act of 1980.
- ☐ The property does not contribute to the significance of the above-named district.
- ☐ The property appears to meet the National Register Criteria for Evaluation and will likely be nominated.
- ☐ The property does not appear to meet the National Register Criteria for Evaluation and will not be nominated.
- ☐ The property appears to contribute to the significance of a:
 - ☐ potential historic district which appears to meet the National Register Criteria for Evaluation and will likely be nominated.
 - ☐ registered historic district but is outside the period(s) or areas of significance as documented in the National Register nomination or district documentation on file with the NPS. Revised nomination or district documentation is enclosed.
- ☐ The property should be denied a preliminary determination that it could qualify as a certified historic structure.
- ☐ Insufficient documentation has been provided to evaluate the structure.

☐ Detailed NPS review recommended ☐ Precedent-setting case ☐ Forwarded without recommendation

Date

8-19-88

State Official Signature



☐ See attachments:

NPS Comments:

Date

NPS Reviewer

CONTINUATION/AMENDMENT SHEET

B-4218

N/A

Property Name

Historic Preservation

Certification Application

828 Park Avenue, Baltimore, Maryland

Property Address

Description of Physical Appearance (continued) - Page 5

Facing an alley called Tyson Street, the west elevation of the carriage house features wide, double-leaf, wood garage doors in a centered opening that is supported by an exposed, painted steel lintel. (See Photo No. 114) Two window openings with brick sills and jack arches flank the garage doors. While one opening retains a double-hung, 4/4 multi-paned wood window, the other contains a corrugated infill panel. At the second floor, two asymmetrically-placed window openings contain corrugated infill panels and panelled wood double-doors fill an opening below a hoist beam.

With the exception of a sealed doorway, the south elevation is blank. (See Photo No. 112) Facing the rear of the townhouse, the east elevation includes a doorway with brick jack arch, panelled wood door, and a glass transom as well as five, sealed window openings. Brick corbelling and a sheet-metal cap complete the east wall. (See Photo No. 111) While the north wall is shared and mostly concealed, the upper portion includes a ventilation stack.

Inside the carriage house behind 828 Park Avenue both levels are open spaces with exposed structure. (See Photo Nos. 103 & 106) Simple wood steps lead from the concrete ground floor to the wood second floor. While most walls are painted brick, some are lined with wood.

A painted brick carriage house at the rear of the lot at 830-832 Park Avenue is connected to the one at 828 Park Avenue. Facing Park Avenue, but recessed over one hundred feet, the east elevation features a wood and glass panelled door and sidelights with a wide wood frame flanked by double-hung, multi-paned wood windows in arched openings. (See Photos Nos. 91 & 110)

Facing Tyson Street, the west elevation features a wide steel garage door flanked by window openings with segmental arches similar to those at the east wall. (See Photos Nos. 113 & 114) One opening retains a double-hung, multi-paned wood window; the other contains glass block.

Inside this carriage house, there are a few panelled wood rooms toward the east end and miscellaneous partitions. (See Photos Nos. 92-96 & 98) Elsewhere, the space is open with view of steel beams, wood roof joists, two gabled skylights, and the second floor loft where headroom is limited. (See Photo No. 100) Formerly exterior brick walls and arched window openings are now enclosed by the steel garage door (See Photo No. 96); the original Tyson Street doorway appears to have been aligned with the west wall of the adjacent carriage house. An interior doorway connects the two carriage houses; a ramp cut into the floor next door accommodates the difference between the two concrete floor levels. (See Photo No. 102)

CONTINUATION/AMENDMENT SHEET

B-4218

Historic Preservation
Certification Application

N/A

Property Name

828 Park Avenue, Baltimore, Maryland

Property Address

Instructions. Read the instructions carefully before completing. Type, or print clearly in black ink. Use this sheet to continue sections of the Part 1 and Part 2 application, or to amend an application already submitted. Photocopy additional sheets as needed.

This sheet: ☒ continues Part 1 ☐ continues Part 2 ☐ amends Part 1 ☐ amends Part 2 NPS Project Number: _____

Description of Physical Appearance (continued) - page 4

In plan, circulation is direct from the Park Avenue entrance to the front hall where the only interior stairway leads to each upper floor. (See Photos Nos. 16 & 32) (There is no interior access to the basement.) The hallway and stair are partially lined with a wainscot of embossed paper with wood chair rail. While vinyl tile covers the hallway floor, the steps are stained wood with rubber-protected treads. Decorative plaster medallions and cornices punctuate the ceiling of the first floor stair hall and the front room just south of it.

Of all of the interior spaces, the front room is most impressive. (See Photos Nos. 17 & 18) It features a herringbone-patterned wood strip floor, a sculptured marble fireplace, and four-over-four double-hung wood windows that extend from floor to ceiling with panelled shutters set into the sides of the window reveals.

Some original interior walls have been altered, including one separating the front room from the room immediately west where the width of the original opening has been reduced. (See Photo No. 19) Some partitions have been added, including ones at or near sealed fireplaces. (See Photos Nos. 21, 27, 28, 46, 84, 86, 88, & 89) Of approximately fourteen fireplaces, seven have been closed.

While the original wood trim, panelled doors, and plaster ceilings remain in many locations, some flush doors, plain trim, blank wood transoms, and acoustical tile ceilings have been added in recent years. (See Photos Nos. 19, 20, 34, 40, 41, 45, & 46)

Name Mr. John McCarthy Signature [Signature] Date 19 July 88
Street 809 Cathedral Street City Baltimore
State Maryland Zip 21201 Daytime Telephone Number (301) 625-5755

NPS Office Use Only

- ☐ The National Park Service has determined that these project amendments meet the Secretary of the Interior's "Standards for Rehabilitation."
☐ The National Park Service has determined that these project amendments do not meet the Secretary of the Interior's "Standards for Rehabilitation."

Date _____ National Park Service Authorized Signature _____ National Park Service Office/Telephone No. _____

☐ See Attachments

CONTINUATION/AMENDMENT SHEET

B-4218

N/A

Property Name

Historic Preservation

Certification Application

828 Park Avenue, Baltimore, Maryland

Property Address

Description of Physical Appearance (continued) - page 3

The south elevation includes three distinct sections. At the east or front section of the south wall, unpainted brick is punctuated by multi-paned, double-hung windows at the basement, first, and fourth floors and crowned by a slight gable and two symmetrically placed chimneys. (See Photos Nos. 6 & 7) Immediately west, a three-storey section of painted brick is seven bays long and crowned by corbelled brick and a shed roof. (See Photo No. 8) Multi-paned wood windows with painted stone sills mark each bay. First and second floor windows are double-hung with brick jack arches; third floor windows at the rear six bays are small casements. This section of the building features a two-storey bay with double-hung wood sash, one over one in configuration of lights. Just to the right of this projecting bay, there is a one-storey stucco addition with one multi-paned wood casement window. (See Photo No. 9) Just to the left of the projecting bay, there are glass panelled double doors with a glass transom. (See Photo No. 26) Two stories high, the west or rear section of the building is stucco and painted brick at the first floor, with asbestos shingles at the second floor, and a shed roof. This patchwork of materials and the roof projection between the first and second floors suggest that parts of this section of the building replaced open areas or porches. (See Attachments C, D, E, & F) The stuccoed section is punctuated by a door; the brick and shingled sections each contain one multi-paned wood window. (See Photo No. 10)

At the east and tallest section of the house, the west elevation is painted brick punctuated at each of the three bays by multi-paned double-leaf wood casements at the fourth floor. (See Photo No. 11) The one bay of the first and second floors not covered by the rear section of the building features one multi-paned double-hung wood window per floor. A metal fire escape, added in 1948, obscures view of this wall.

Two stories high, the west elevation of the rear of the building is partially obscured from view by the carriage house at the rear of the lot. The left half of the wall is painted brick with a chimney at the upper left corner of the shed roof. (See Photo Nos. 10 & 11) This rear section of the building covers all but the third floor brick, double-hung wood window, and shed-roof silhouette of the part of the building immediately to the east. (See Photo No. 12)

CONTINUATION/AMENDMENT SHEET

Historic Preservation
Certification Application

RECEIVED

B-4218

JUL 20 1989

N/A

Property Name

828 Park Avenue, Baltimore, Maryland

Property Address

Instructions. Read the instructions carefully before completing. Type, or print clearly in black ink. Use this sheet to continue sections of the Part 1 and Part 2 application, or to amend an application already submitted. Photocopy additional sheets as needed.

This sheet: ☒ continues Part 1 ☐ continues Part 2 ☐ amends Part 1 ☐ amends Part 2 NPS Project Number: _____

Description of physical appearance (continued) - Page 2

The Park Avenue facade of the townhouse features an entrance that is approached by marble steps, flanked by marble cheek walls and plain iron handrails, and crowned with a bracketed wood cornice above an arched glass transom. (See Photo No. 3) An open vestibule with black and white marble tiled floor leads to double doors with plain wood panels and etched glass below another glass transom.

Three bays wide, the exposed brick facade sits upon a coursed stone base that is punctuated by openings for a glass and wood panelled basement door, its glass transom, and a window opening containing an air conditioner and wood infill. (See Photo No. 4) Brick steps lead down a well that is lined with brick and guarded by a simple iron rail.

Above, the brick facade is punctuated by equally spaced double-hung, multi-paned wood windows of diminishing heights. (See Photo No. 2) Each window has a stone sill. First and second floor windows feature stone hoods while third floor windows show brick jack arches. Third and fourth stories were added circa 1855 as indicated by changes in the masonry that occur at the third floor window aprons and continue up to the bracketed and panelled wood cornice that surmounts the facade.

Painted brick, the north wall is punctuated only by two narrow windows at the second floor. Two painted brick chimneys appear at the rear section. (See Photo No. 5)

Name Mr. John McCarthy Signature J. John McCarthy Date 19 July 89
Street 809 Cathedral Street City Baltimore
State Maryland Zip 21201 Daytime Telephone Number (301) 625-5755

NPS Office Use Only

- ☐ The National Park Service has determined that these project amendments meet the Secretary of the Interior's "Standards for Rehabilitation."
☐ The National Park Service has determined that these project amendments do not meet the Secretary of the Interior's "Standards for Rehabilitation."

Date _____ National Park Service Authorized Signature _____ National Park Service Office/Telephone No. _____
☐ See Attachments

HISTORIC PRESERVATION CERTIFICATION APPLICATION— PART 1

NPS Office Use Only

N/A

Property Name

Project Number:

828 Park Avenue, Baltimore, Maryland

Property Address

5. Description of physical appearance:

Almost 24 feet wide at the east facade and about 17 feet wide at the west end, this masonry, three and one-half storey, detached townhouse extends approximately 101 feet in length. A small, planted area separates the building from a two-storey brick carriage house that occupies the rear portion of the lot. Roughly 26 feet wide, the lot includes a narrow, paved passage that runs along the south side of the townhouse and terminates at a former gateway, sealed with plywood, at the Park Avenue sidewalk. The adjacent iron fence and brick garden wall guard an undeveloped lot at 826 Park Avenue that separates the building from its neighbor to the south. (See Photo No. 1) North of the house, the lot at 830-832 Park Avenue is planted but vacant except for a paved path that leads to a carriage house at the rear. (See Photo No. 91)

Date of Construction: circa 1840 Source of Date: visual inspectionDate(s) of Alteration(s): circa 1855: third & fourth stories added: circa 1900, 1910, & 1930: See

Attachments C, D, E, & F; 1946, 1948 & 1961: See Attachment G

Has building been moved? ☐ yes ☒ no. If so, when?

6. Statement of significance:

Considered the heart of Baltimore City, Mount Vernon Place Historic District is a fine example of nineteenth century urban planning. It features an architecturally significant cluster of cultural institutions, churches, and residences surrounding the Washington Monument. Its historical and cultural significance is based upon its representation of Baltimore's four great philanthropists and their contributions to the City.

Constructed circa 1840 as a two and one-half storey townhouse, third and fourth stories were added circa 1855. The Italianate rowhouse at 828 Park Avenue is similar in size, scale, materials, and style to the majority of buildings that immediately surround it. (See Photos. Nos. 13 & 14) This townhouse, including servants' quarters and basement, was converted to doctors' offices and apartments in 1946. (See Attachment G)

7. Photographs and maps.

Attach photographs and maps to application.

Continuation sheets attached: ☒ yes ☐ no

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

RECEIVED
OMB Approved
No. 1024-0009

B-4218

JUL 20 1988

HISTORIC PRESERVATION CERTIFICATION APPLICATION
PART 1 — EVALUATION OF SIGNIFICANCE

NPS Office Use Only

NRIS No:

MARYLAND HISTORICAL
TRUST
Project No:

Instructions: Read the instructions carefully before completing application. No certification will be made unless a completed application form has been received. Type or print clearly in black ink. If additional space is needed, use continuation sheets or attach blank sheets.

1. Name of property: N/A
Address of property: Street 828 Park Avenue
City Baltimore County _____ State Maryland Zip 21201
Name of historic district: Mount Vernon Place Historic District
☒ National Register district ☐ certified state or local district ☐ potential historic district

2. Check nature of request:

- ☒ certification that the building contributes to the significance of the above-named historic district for the purpose of rehabilitation.
☐ certification that the structure or building and, where appropriate, the land area on which such a structure or building is located contributes to the significance of the above-named historic district for a charitable contribution for conservation purposes.
☐ certification that the building does not contribute to the significance of the above-named district.
☐ preliminary determination for individual listing in the National Register.
☐ preliminary determination that a building located within a potential historic district contributes to the significance of the district.
☐ preliminary determination that a building outside the period or area of significance contributes to the significance of the district.

3. Project contact:

Name Ms. Hattie F. Russell, David H. Gleason Associates, Inc.
Street 616A North Eutaw Street City Baltimore
State Maryland Zip 21201 Daytime Telephone Number (301) 728-1810

4. Owner:

I hereby attest that the information I have provided is, to the best of my knowledge, correct, and that I own the property described above. I understand that falsification of factual representations in this application is subject to criminal sanctions of up to \$10,000 in fines or imprisonment for up to five years pursuant to 18 U.S.C. 1001.

Name Mr. John McCarthy Signature [Signature] Date 19 July 88
Organization Baltimore Historic Properties II
Social Security or Taxpayer Identification Number applied for
Street 809 Cathedral Street City Baltimore
State Maryland Zip 21201 Daytime Telephone Number (301) 625-5755

NPS Office Use Only


The National Park Service has reviewed the "Historic Preservation Certification Application — Part 1" for the above-named property and hereby determines that the property:

- ☐ contributes to the significance of the above-named district and is a "certified historic structure" for the purpose of rehabilitation.
☐ contributes to the significance of the above-named district and is a "certified historic structure" for a charitable contribution for conservation purposes in accordance with the Tax Treatment Extension Act of 1980.
☐ does not contribute to the significance of the above-named district.

Preliminary Determinations:

- ☐ appears to meet the National Register Criteria for Evaluation and will likely be listed in the National Register of Historic Places if nominated by the State Historic Preservation Officer according to the procedures set forth in 36 CFR Part 60.
☐ does not appear to meet the National Register Criteria for Evaluation and will likely not be listed in the National Register.
☐ appears to contribute to the significance of a potential historic district, which will likely be listed in the National Register of Historic Places if nominated by the State Historic Preservation Officer.
☐ appears to contribute to the significance of a registered historic district but is outside the period or area of significance as documented in the National Register nomination or district documentation on file with the NPS.
☐ does not appear to qualify as a certified historic structure.


Date _____ National Park Service Authorized Signature _____ National Park Service Office/Telephone No: _____
☐ See Attachments



W. MADISON STREET

ATTACHMENT J.
Planometric Map, Scale: 1" = 100'.
Key to Photographs

828 Park Avenue
Baltimore, Maryland







ATTACHMENT A
City Atlas of Baltimore, MD
& Environs, 1876

828 Park Avenue
Baltimore, Maryland

PA WAR BAL




W. MADISON



RT OF DS 8&11 ly of TIMORE

5


Scale 80 feet to 1 inch.



ATTACHMENT B.
Atlas of the City of Baltimore,
Northwest Section, Vol. 1., 1885

828 Park Avenue
Baltimore, Maryland





THESE
BLDG'S
NO LONGER
EXIST.



PARK

FIRST
PRESBYTN
CHURCH

ATTACHMENT C.
Sanborn Fire Insurance Map,
Baltimore, MD, 1890

828 Park Avenue
Baltimore, Maryland

B-4218



ATTACHMENT D.
Sanborn Fire Insurance Map,
Baltimore, MD, 1902

828 Park Avenue
Baltimore, Maryland

B-4218

BALTIMORE COLLEGE,
OF DENTAL SURGERY

MARBLE SHOP

TYSON ST.

SUNDAY SCHOOL
CHAPEL

1ST PRESBYN.
CHURCH

35' TO DRIVE
ABOUT 1.5' OVERLAP
LAWYER'S ELEC.

PARK AV.

6" W. PIPE

6" W. PIPE

ATTACHMENT E.
Sanborn Fire Insurance Map,
Baltimore, MD, 1914

828 Park Avenue
Baltimore, Maryland

B-4218

W. MADISON

W. PIPE

6"

(113)

D.

5/8/46	REPAIR FLR. JOISTS, PARTITIONS
5/24/46	ALTER FOR & USE FOR APTS & DOCTORS' OFFICES
2/27/48	ERECT (2) STEEL FIRE ESCAPES
/61	USE FOR DRS. OFFICES.

OVER

THIS LIST OF
APPLICATIONS IS
DEIPHERED
ABOVE.

LOCATION *1215 N. ...*
OWNER *(126 ...)*
OCCUPANCY *CLASS*
HEIGHT *1*
VOLUME *...*

DIV *11*
SEC *9*
BLK *509*
LOT *8*
H L DG

APPLICATION NUMBER	PURPOSE OF APPLICATION	DATE OF COMPLETION	REMARKS
<i>5/8/46</i>	<i>Repair floor joists, partitions</i>	<i>...</i>	<i>...</i>
<i>5/24/46</i>	<i>Alter for use for apts & doctors' offices</i>	<i>...</i>	<i>...</i>
<i>2/27/48</i>	<i>Erect (2) steel fire escapes</i>	<i>...</i>	<i>...</i>
<i>10/4/61</i>	<i>Use for Drs. offices</i>	<i>...</i>	<i>...</i>

ATTACHMENT G.
Baltimore City Permit Applications
City Archives

828 Park Avenue
Baltimore, Maryland

B-4218

ARMORY PL

DEN AVE

N HOWARD ST

TYSON ST

EAD-HADISON

PARK AVE

W READ ST

BREXTON ST

CATHEDRAL ST

PLOY ST

B-4218

GIS data Courtesy of
the City of Baltimore, MOIT/EGIS

